



Sanitary Sewer Overflow Annual Report

Division of Surface Water

Date: 03/03/2026		
Facility Name: New Carlisle WWTP		
Ohio NPDES Permit Number: 1PD00018*JD		
Period Covered by Report: 01/01/2025 - 12/31/2025		
Contact Person: Kerri May		Title: Wastewater Superintendent
Mailing Address: 331 S. Church St, PO BOX 419		
City: New Carlisle	State: OH	Zip Code: 45344
Country: USA		
Sanitary Sewer Overflows Spreadsheet(attachment) : SSOWorksheet2025.xlsm		
Water In Basement Occurrences Spreadsheet(attachment) : WIB form2025.xlsm		
Narrative analysis of WIB patterns by location, frequency and cause: <i>There has been only 2 WIB occurrences in the last 2 years. Both Have been caused by rags (flushable wipes) getting stuck in the sewer lines.</i>		
ADDITIONAL INFORMATION		
<i>Please add any additional comments or attachments below.</i>		
Certification		
<i>I certify under penalty of law that I have personally examined and am familiar with the information in this report and all attachments. Based on my inquiry of those persons immediately responsible for obtaining the information contained in the report, I believe that the information is true, accurate, and complete.</i>		
Name: Kerri May		Title: Wastewater Superintendent
Signature(Electronically submitted by):		Submission Date: 03/03/2026

The full report may be found at the Water Reclamation Plant, via request.